## AMENDMENTS TO THE SPECIFICATION:

Paragraph beginning at page 12, line 11:

The driver 3 supplies the three-phase armature current to the armature 4 in response to the measured electromotive voltages. The driver 3 supplies the three-phase armature current through the U-phase line 9a, the V-phase line 9b and the W-phase line  $9\underline{c}$  to the armature 4.